

**NOTE ON POST-DISASTER PRELIMINARY GEOLOGICAL STUDIES OF THE  
KOTLEN LANDSLIDE ALONG NH-37 (IMPHAL-JIRIBAM ROAD), 5 Km SSW OF  
KOTLEN, NONEY DISTRICT, MANIPUR**

By:

**Visahono Zaphu, Sr. Geologist**

Project Landslide, GSI-NER, Dimapur

&

**Lorhienu Tase, Assistant Geologist**

Project Landslide, GSI-NER, Dimapur

*Under the Supervision of:*

**S. P. Dhanvijay**

Director,

Project Landslide, GSI-NER, Dimapur

**Abstract**

Preliminary geological appraisal of a landslide was carried out along NH-37 (Imphal-Jiribam road) situated 5 km SSW of Kotlen, Noney district, Manipur. The incident occurred on 12.06.2018 and damaged the road bringing vehicular movement to a halt. A post disaster investigation of the reported site was undertaken with an objective to understand its causative factors, failure mechanism in order to recommend short term remedial measures. The landslide is approximately 95 meters in length and 130 meters in width with run out distance of about 200 metres flowing NW to Kharam Lok stream below the road. Slide area encompasses variably weathered, rocky mass of Disang Formation. Delineated slide mass consists of grey splintery shale, siltstone and sandstone. The landslide has been caused by failure of overburden material due to increased pore water pressure resulting from incessant rainfall and toe erosion by the stream. Hence the landslide has been categorized as “deep planar failure” in terms of the failure mechanism. Based on the stability assessment of the slope forming materials as well as consideration of the elements at risk, short term remedial measure like construction of a lined drainage along the road, quick removal of overburden materials, channelling and diversion of rain water in the crown portion etc., has been suggested to the agency (HVS) managing the highway.

**Background Information**

Preliminary investigation of the landslide was taken up on priority basis by the team from Geological Survey of India, State Unit: Manipur and Nagaland, Dimapur on 23.06.2018. The massive landslide occurred along NH-37 about 5 kms SSW of Kotlen. The landslide located at Lat: 24° 47' 28.7"N and Long: 93° 44' 8.4" E is about 39 kms from Imphal. The slide is on the WSW facing slope along NH-37 (Imphal-Jiribam) towards the

SSW of Kotlen, Noney district, Manipur (Photo 1). The affected area falls in SOI Toposheet no. 83 H/09 and the detail of the slide is provided in Annexure-I. At other places along the NH-37, 12 nos. of landslides of medium to small sizes has also been observed and respective latitudes and longitudes are mentioned Annexure-II.

A second order perennial stream flows towards the right flank of the slide. Prior to the slide the area received heavy rainfall for many days. The slide was initiated on 12.06.2018 at around 18:00 hrs causing blockage to the highway. The authority maintaining the highway (HVS) cleared the debris to facilitate vehicular movement. Again the slide got reactivated in the early hours of 22.06.2018 and brought the vehicular movement to a halt on either side of the road. The highway authority (HVS) worked with heavy machinery to clear the debris off the road to ease the vehicular movement. There was no report of casualties except damage to the cable wires. The dimension of landslide is 95 meters in length and 130 meters in width with run out distance of about 200 metres (Photo 2).

### **Physiography and Drainage**

The terrain comprises of highly rugged hill ranges partially capped by sandstone cliffs and intervening deep valleys, which are invariably drained by perennial streams. It is represented by long linear ridges/hill ranges and valleys with its highest and lowest elevation of 1925m and 340m above mean sea level at points ENE of Wapang Jhongjong hill and NNE of Noney (along the Ijai river), respectively. The hills show north-easterly as well as north-westerly trends. The area is drained by the Ijai, the Iring and the Tupul rivers which follow the structurally weak zones. Drainage pattern in the area is dendritic while some of the small tributaries/ rivulets exhibit rectangular drainage pattern which is indicative of joint or fault controlled drainage system.

### **Site Geology**

The geology around the landslide site exposes Disang Formation consisting of bedded grey shales with thin partings of fine grained sandstones. The shale is splintery in nature. Ripple marks were observed in the competent sandstone beds which are also well jointed.

### **Slide Morphometry and Material**

The slide measures 95m length, 130m width, 4m depth, 90m height and a total runoff of 200m. Failure mechanism is deep planar failure. The slide material is mainly transported soil derived from weathered shale of Disang Formation from upslope and the thickness is more than 6m.

## Structural data

The trend of the bed in the study area is NNW-SSE ( $350^{\circ}/47^{\circ} \rightarrow 260^{\circ}$ ). Joints have been recorded in all the rock types of Disang Group. Sandstone beds show four sets of joints. The predominant sets of joints recorded in the area are: i)  $J_1$ :  $290^{\circ}/76^{\circ} \rightarrow 20^{\circ}$ , ii)  $J_2$ :  $215^{\circ}/62^{\circ} \rightarrow 125^{\circ}$  iii)  $J_3$ :  $60^{\circ}/78^{\circ} \rightarrow 150^{\circ}$  and iv)  $J_4$ :  $105^{\circ}/66^{\circ} \rightarrow 15^{\circ}$  along which sliding of the unconsolidated weathered materials occurred (Fig:1)




Fig:1. Stereographic representation of the structural data.

## Characterization of the slide material

The rock debris material is mainly constituted by the lithic arenite material of Upper Disang Formation. This overall material is grey in colour, soil with minor clay content and rock fragments derived from shale portion of the rock mass. The fresh overburden material was occupying the gap area and resting over the Disang rock.

The material excavated from the uphill side of the road and consisting of alternate sandstone and shale of Disang Formation was dumped on the downslope side of the road.

## Failure Mechanism of the Landslide

The failure mechanism of this landslide is categorised as deep planar failure. It is directly related to the type and nature of material, disposition of the beds, road cutting etc. In addition to reduced rock mass strength due to saturation and unfavorable orientation of joints and fractures, the intensity and effect of landslide in the area increased with various geomorphic factors such as steepness and height of slopes, water ingress in rock joints and fractures, saturation of rock material due to heavy rains. Again, anthropogenic factors as a result of developmental activities such as poorly designed roads and encroachment on steep

slopes, further aggravated the process. Due to incessant heavy rainfall high infiltration of water caused increase in pore pressure, volume, saturation and weight and decrease in load bearing capacity and cohesion of the material. As a result, material in the slope collapsed and slid down along the planes.

### L-Section of landslide

A section along AB line was prepared on 1:1000 scale (Fig. 2), to delineate shape of the slide and disposition of slided material along the length of the slide. Trend of AB line is 295°-125°.




Fig: 2. L-section along AB line.

### Causative Factors of the Landslide

Based on the preliminary investigation and analysis of the collected data, it has been interpreted that the landslide had occurred due to a combination of the factors, summarised below:

1. Failure of overburden material due to increased pore water pressure as a result of incessant rainfall.
2. Probable extensive slope cut for communication thereby aggravating the instability of the slope.
3. Inherent poor rock mass i.e. the rocks are profusely jointed and composed of splintery grey shale, thinly bedded sandstone and siltstone.
4. Unguided down slope flow of surface runoff from the road.
5. Toe erosion by the stream at the base of the slope.

### Field-based Stability Assessment


1. The landslide has occurred in the mid-slope where the NH-37 is aligned.

2. The slope is moderately dissected and the slope angle is moderate but the slope below the NH is relatively steep  $>45^\circ$ .
3. The slope hosts variably thick (2-5m) debris overburden (transported soil) and is sparsely vegetated.
4. The slide is on the WSW facing slope along NH-37 and the attitude of the rock exposure is  $S_{0-350^\circ}/47^\circ \rightarrow 260^\circ$  which also gives the dip direction of the slope. The overburden slid along the bedding plane and their interface provided a passage for the percolating water which acted as a lubricant along the bedding plane and drastically reduced the shear parameters of the soil material.
5. Lack of a lined drain along the road led to percolation of surface runoff into the weak rockmass.
6. The dimensions of the landslide are 95 m length x 130m width x  $> 2$  m depth with run out distance of about 200 metres flowing to the stream below the road. The height of the landslide is estimated as 90m upto road level and total inclined height (Length of slide) is around 220 m (up to stream).
7. No cracks were observed in the proximity of the crown.
8. Debris were still sliding at the time of investigation and JCB excavators were employed by the authority (HVS) for clearing the debris to let vehicles ply from both sides (Photo 3).
9. Dumping of slided material towards the downslope side of the road have increased the runoff distance.

### **Recommended remedial measures**

1. Removal of the loose overburden debris in the upslope portion (which is already been carried out by the road maintenance agency) Photo 3.
2. Channelling and diversion of rain water in the crown portion away from the slide area by constructing lined contour drains.
3. Lined contour and cross drainage to divert the surface runoff away from the road.

## Photographs



**Photo 1:** Location of the slide from Google Earth imagery



**Photo 2:** Perspective view of slide Kotlen landslide.



**Photo 3:** Slide area showing debris on the failure plane. Heavy machinery engaged in clearing and removal of debris.

### Geoparameter data sheet (42-points) Annexure-I

1	Slide	MN/NON/83H/9/2018/0006
2	State	Manipur
3	District	Noney
4	Toposheet	83 H/09
5	Name of the slide	5 Km SSW of Kotlen Landslide (NH-37)
6	NH/SH/Locality	NH-37/ Imphal-Jiribam Highway/ 5Kms from Kotlen towards Noney.
7	Latitude	24°47'28.7"N
8	Longitude	93°44'8.4"E
9	Length	95m
10	Width	130m
11	Height	90m
12	Area	12,350sq m
13	Depth	≈ 6m
14	Volume	74100 cubic m (approx)
15	Run out distance	200m (approx)
16	Type of material	Debris
17	Type of movement	Slide
18	Rate of movement	Rapid
19	Activity	Active
20	Distribution	Advancing
21	Style	Multiple
22	Failure mechanism	Deep translational failure
23	History	Initiated on 12.06.2018 and reactivated on 22.06.2018
24	Geomorphology	The slide formed on a moderately dissected slope of the hill.
25	Geology	Alternate beds of shale and sandstone.
26	Structure	$S_0=350^\circ/47^\circ \rightarrow 260^\circ$ , $J_1=290^\circ/76^\circ \rightarrow 020^\circ$ , $J_2=215^\circ/62^\circ \rightarrow 125^\circ$ , $J_3=060^\circ/78^\circ \rightarrow 150^\circ$
27	Landuse/landcover	Sparse vegetation.
28	Hydrological condition	Dripping
29	Triggering factor	Rainfall
30	Death of persons	Nil
31	People affected	Nil
32	Livestock loss	Nil
33	Communication	NH-37 road blocked.
34	Infrastructure	Road damaged for a length of 130m and cables damaged
35	Agriculture/ Forest/ Barren	Barren
36	Geoscientific causes	<ol style="list-style-type: none"> <li>1. Extensive slope cut for communication aggravated the instability of the slope.</li> <li>2. Inherent poor rock mass i.e. the rocks are profusely jointed and composed of splintery grey shale.</li> <li>3. Failure of overburden material due to increased pore water pressure as a result of incessant rainfall.</li> <li>4. Unguided down slope flow of surface runoff from the road.</li> </ol>

37	Remedial measures	<ol style="list-style-type: none"> <li>1. Removal of overburden materials.</li> <li>2. Channelling and diversion of rain water in the crown portion.</li> <li>3. Lined drainage along the road.</li> <li>4. A retention wall with proper weep holes to be constructed on the slope of the NH-37. A culvert across the NH to</li> </ol>
8	Remarks, if any	
39	Photos, sketch of the plain and section of the slide	Refer Fig. 1, Photo 1, Photo 2, Photo 3
40	Landslide Category	Category- II.
41	Summary	
42	Pdf	Enclosed

